

序号	委托单位	报告编号	检测日期	检测结论	现场检测照片	备注
1	邹平梁邹矿业有限公司	QAJC4-BG-GSS-0444-2024	2024年11月29日	合格	 A technician wearing a red jacket is seated at a desk, operating a piece of laboratory equipment. The equipment has a control panel with a digital display and various buttons. The technician is looking at the equipment. The background is a plain white wall. A timestamp in the bottom left corner of the photo reads "2024-11-29 11:44 中国, 山东省, 淄博 市".	/
2	邹平梁邹矿业有限公司	QAJC4-BG-GSS-0478-2024	2024年12月20日	合格	 A technician wearing a red jacket is standing and operating a large piece of laboratory equipment. The equipment is a tall, white cabinet with a glass door. The technician is looking at the equipment. On the wall behind the technician is a yellow warning sign with a black triangle and the text "当心机械伤人". A computer monitor is visible on a desk in the foreground. A timestamp in the bottom left corner of the photo reads "12月20日 2024 星期五". In the bottom right corner, there is a logo for "今日水印" (Today's Watermark) with the text "水印相机" and "www.xunluo.com".	/